

# Mini Leveling Base Mounting Instructions



**1.** Please start by removing the protective cap shown in STEP 1.



**2.** After you install the leveling base on your tripod, insert the 1/4-20 locking screw into one of the 3 threaded holes in the leveling base and use enclosed hex wrench to securely tighten the screw. **The hex wrench and screw are enclosed in the packet with the red label.**

## General leveling base features

